














Assembly Instruction













PARTS LIST




NO.	QTY.	LINEDRAWING
(A)	17	 7x50mm
(B)	37	
(C)	37	
(D)	15	 8x40mm
(E)	24	 3.5x30
(F)	16	
(G)	5	 6x25
(H)	8	 6x50
(I)	17	
(J)	37	
(K)	8	

NO.	QTY.	NO.	QTY.
(1)	1	(12)	1
(2)	1	(13)	1
(3)	1	(14)	1
(4)	1	(15)	1
(5)	1	(16)	1
(6)	1	(17)	1
(7)	1	(18)	6
(8)	2	(19)	1
(9)	1	(20)	2
(10)	1	(21)	1
(11)	1	(22)	1
		(23)	1


1




2




3




4




5




6




7




8




9




10




11




12




13




14




15




16




17




18




19




20




21




22




23



24



25



26

